







Fernanda



Benötigte Werkzeuge – Outils Nécessaires – Tools Required – Attrezzi Necessari




A x2




L & R

B x2



G x2




790 02512

C x2



H x4


M8x25



631.10/00

D x2

M8x20



I x4



631.402


E x8

Ø4x20



K x2

Ø4x16



631.3300

F x2







J x1





631.10000



1420 000x




2.




3.



I x1



V x8
18x50




631.01500

I x8



631.402

II x8



631.62100

/ x1



631.10000

